



LuK 0562

SERVICE INFO

Installation notice

Guide tube issues

Manufacturers : Kia
 Models : Sportage
 Picanto
 Engines : Various

As with all vehicles using a release bearing and fork assembly it is crucial that the guide tube is in a servicable condition. On many of the Kia range the guide tube is an integral part of the bellhousing and can only be replaced as a complete assembly.



Excessive wear to the guide tube can result in heavy clutch operation, clearance problems or failure of the release bearing or fork.

- For accurate model information please see the Schaeffler online catalogue
- Die genaue Fahrzeugzuordnung entnehmen Sie bitte dem Schaeffler- Katalog
- Pour plus d'information sur les applications veuillez vous référer au catalogue Schaeffler
- Para obtener información sobre el modelo, rogamos consulte el catálogo de Schaeffler
- Per informazioni sul modello consultare il catalogo Schaeffler

REXPERT Hotline: +44 (0) 1432 264264
 Fax: +44 (0) 1432 375 760
 E-Mail: aftermarket.uk@schaeffler.com
www.rexpert.co.uk

Issued 07 2018 / LuK 0562 / Technical content subject to change
 OE Manufacturer's names and numbers are used for reference purposes only
 © Schaeffler Automotive Aftermarket

